



Structurally Deficient Bridges on the National Highway System

2nd Congressional District of Minnesota, 2003



Legend

- Structurally Deficient Bridges
- Cities
- Airports
- Amtrak Stations
- Interstate Highways
- US Highways
- State Highways
- Amtrak Routes
- Other Rail Lines
- Navigable Waterways
- Minnesota District 2
- Urbanized Areas
- Park Facilities
- Military Bases



| | Structure Number | Road | Location |
|---|------------------|---------|--------------------------|
| 1 | 6773 | USTH 61 | 1.6 MI NW OF S JCT TH 63 |
| 2 | 66803 | ISTH 35 | AT JCT TH 19 |
| 3 | 66804 | ISTH 35 | AT JCT TH 19 |



U.S. Department of Transportation
Bureau of Transportation Statistics
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.